

FAQ

NR: 047

SOFTWARE: RAWCONVERTER

The 3D-VIZ TOOL already begins to generate a file before all the photographs have been taken.

Make sure, that in Capture One only one specification for exporting the pictures is active.